



Product: SiS Integrated 10/100 Fast Ethernet

Date: 07/21/2000

Document Type: Release Note

Driver Ver.: 1.10.01

Integrated LAN Driver [V1.10.01]

1. Windows98 driver, Windows2000, and WindowsNT4.0 submitted to WHQL for PC'99 logo. Not certified by WHQL yet. No .cat file and bit-flip driver available in this package. WindowsME driver not submitted at this release.
2. Support 630S for testing w/ external phy ICS1893 and phy address must set to be 1.
If you want to test 630S, the manufacture test program and DOS diagnostic program must be updated to v1.01 and v1.51, respectively.
3. Setup utility to support automatic installation on WinME.
4. Bug fixed, Modification & Driver Version
 - (1) [Windows 2000]
 - a. INF update to add customers' SSID/SVID
 - b. Support 630S for testing w/ external phy ICS1893 and phy address must set to be 1
 - (2) [Windows 98/98SE]
 - a. Fix that: blue screen occurs when connecting Ethernet adapter to ADSL modem.
 - b. INF update to add customers' SSID/SVID
 - c. Support 630S for testing w/ external phy ICS1893 and phy address must set to be 1
 - (3) [Windows Me]
 - a. Support 630S for testing w/ external phy ICS1893 and phy address must set to be 1
 - (4) [Windows NT40]
 - b. Support 630S for testing w/ external phy ICS1893 and phy address must set to be 1
 - (5) [Windows 95/95OSR2]
 - a. Support 630S for testing w/ external phy ICS1893 and phy address must set to be 1
 - (6) [Windows 9x/2000 setup utility]
 - a. Support WinME driver install
 - (7) [DOS Diagnostic Utility]
 - a. Support 630S.
 - (8) Driver Version: (*: updated)

Windows 2000 -----	1.10.00*
Windows 98 -----	1.10.00*
Windows Millennium -----	1.10.00*
Windows 95 OSR2 -----	1.10.00*
Windows 95 -----	1.10.00*
Windows NT 4.0 -----	1.10.00*
Windows for Workgroup -----	1.10.00*



Netware server 3.12 -----	1.08*
Netware server 4.1x -----	1.08*
Netware server 4.2 -----	1.08*
Netware server 5.0 -----	1.08*
Netware client32 -----	1.08*
Netware client -----	1.08*
Packet driver -----	1.08*
NDIS 2 for DOS -----	1.08*
MS LAN Manager -----	1.08*
NDIS 2 for OS/2 -----	1.08*
SCO 5 -----	1.06
DOS Diagnostic program -----	1.51*
Windows 9x/2000 setup utility--	1.10*
BootROM Rpl(16K, Int18) -----	1.05
BootROM Rpl(16K, Int19) -----	1.06
BootROM Rpl(16K,SiS630E,S) -	1.08*
BootROM Rpl(32K) -----	1.08*
BootROM PXE -----	1.01*